

BUREAU VERITAS

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of "Consigne de Navigabilité"  
Réf. : 88-167-034(B)  
In case of any difficulty, reference should  
be made to the French original issue.

## AEROSPATIALE SA 341 G / 342 J (GAZELLE) Helicopters

Low frequency low landing gear  
Checking for corrosion and improved inside protective treatment

This Airworthiness Directive applies to AEROSPATIALE SA 341 G and SA 342 J helicopters fitted with low frequency low landing gear units comprising :

- forward arch P/N 341A41-5231-05
- aft arch P/N 341A41-5232-06
- aft cross-beam P/N 341A41-5201-03

which were put into service between January 1, 1984 and January 1, 1988.

**NOTE :** All the above assemblies delivered as spares during this period, whether they are currently installed on aircraft or held as spares, are concerned by this Directive.

In order to prevent, or if necessary treat, the formation of corrosion on the inside surfaces of the above components, the following measures are rendered mandatory, from the effectivity date of this Airworthiness Directive :

- within the next 400 flying hours, and in all cases within the next 18 months (or before putting components which are held as spares into service), check the components for corrosion and, if applicable, take the appropriate corrective action in accordance with the instructions given in paragraph I.C "Description" of AEROSPATIALE SA 341-342 S.G. n° 05-24.

---

Cf. : AEROSPATIALE SA 341-342 S.B. n° 05-24

---

**EFFECTIVE DATE : DECEMBER 7, 1988**

November 30, 88

AEROSPATIALE SA 341 G - SA 342 J  
(GAZELLE) Helicopters

Ref. : 88-167-034(B)