

AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 89-057-036(B)
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE AS 332 Helicopters

Fire extinguishing percussion system

This Airworthiness Directive applies to AEROSPATIALE AS 332 helicopters not modified to AMS 332. A. 07.23375.

In order to facilitate action on the fire extinguishing percussion system control pushbuttons, protected by a frangible disc, the following measures shall mandatorily be applied on the date this Airworthiness Directive takes effect.

After the last flight of the day, perform the required checks and, if necessary, replace the fire extinguishing percussion system frangible discs in compliance with the instructions laid down in AEROSPATIALE Telex Service 01-25.

Note : These measures shall have been taken on every percussion system frangible disc held as spare before installation on aircraft.

—
Cf. : AEROSPATIALE Telex Service 01-25
—

EFFECTIVE DATE : 15 AVRIL 1989

Date : April 5,89

AEROSPATIALE AS 332 helicopters

Réf. :89-057-036 (B)