

AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 89-077-021 (B)R2
In case of any difficulty, reference should
be made to the French original issue.

ATR 42 aircraft all types

Aileron tab inboard hinge-pin

The present airworthiness directive applies to ATR 42 aircraft all types, serial numbers 3 to 133 and 135 inclusive.

In order to avoid the displacement of the aileron tab inboard hinge-pin which may disturb the aileron operation and deteriorate the surrounding structure, the following measures are made mandatory.

- 1/ Within 8 days after receipt of this airworthiness directive. Check that the locking of the aileron tab hinge pin is correct, according to the instructions of inspection Bulletin Service ATR 42-57-0028 rev.1.
- 2/ Before November 01, 1989 fit the aircraft with the locking systems of the aileron tab as per Bulletin Service ATR 42-57-0030(mod 2211)

Cf. : B.S ATR 42-57-0028 rev.1
ATR 42-57-0030

The present AD cancels and replaces the AD 89-077-021(B)R1 of May 31, 1989

EFFECTIVE DATE : UPON RECEIPT

July 19, 1989

ATR 42 aircraft all types

Réf. : 89-077-021 (B)R2