

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 89-093-022(B)
In case of any difficulty, reference should
be made to the French original issue.

ATR 42 Aircraft

Automatic cut-off of the voice recorders

This Airworthiness Directive applies to the ATR 42 aircraft, all serial numbers 123 to 142 included, fitted with modification 1848 and not fitted with modification 2311.

In order to restore the automatic cut-off of the cockpit voice recorder 5 minutes after the shutdown of both engines, the following measures are made mandatory whenever the voice recorder is required by the operating regulations.

By August 1st, 1989, modify the voice recorder supply system according to the instructions of S.B. ATR 42-23-0018 (Mod. 2311).

Ref. : Bulletin Service ATR 42-23-0018

EFFECTIVE DATE : JULY 7TH, 1989

June 28, 1989

ATR 42 aircraft
all types

Ref. : 89-093-022(B)