

AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 89-120-023(B)R1
In case of any difficulty, reference should
be made to the French original issue.

ATR 42 series airplanes

Procedures for flight in icing conditions

This Airworthiness Directive applies to all models ATR 42 series airplanes.

- 1) Following incidents caused by the non-respect of procedures applicable to the flight in icing conditions, the incorporation of revisions to the DGAC approved Flight Manual up to revision 6, dated August 1988, inclusive, is required from the effective date of this Airworthiness Directive.
- 2) To minimize the risk in the future of a non-respect of these amended procedures, the installation on all models ATR 42 series airplanes of the "Anti-Icing Advisory System" in accordance with the Service Bulletins listed below is required before November 30th, 1989.

Modifications	Service Bulletins	
1794	ATR 42 - 30 - 0018)
1710	ATR 42 - 30 - 0017)
1826	ATR 42 - 30 - 0025) or later
0564 and 0852	ATR 42 - 27 - 0021) approved revisions
1830	ATR 42 - 27 - 0029)
1827	ATR 42 - 30 - 0027)
1828	ATR 42 - 30 - 0021)

The present revision I cancels and replaces the original AD 89-120-023(B) of August 23, 1989

EFFECTIVE DATE : UPON RECEIPT

September 20, 89

ATR 42 series airplanes

Ref. : 89-120-023(B)R1