

BUREAU VERITAS

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of "Consigne de Navigabilité"  
Réf. : 89-135-037(B)  
In case of any difficulty, reference should  
be made to the French original issue.

## AEROSPATIALE AS 332 helicopters

HF-SSB wire antenna

This Airworthiness Directive applies to all AS 332 helicopters (all versions) equipped with the HF-SSB installation which has not been modified according to sketch 332 PCS 54050.

With a view to ensuring the safety of all aircraft fitted with this installation, the following measures are rendered mandatory from the effectivity date of this Airworthiness Directive :

- within the next 50 flying hours, bind the double swivels and the antenna retaining wire, as described in the appendix corresponding to the type of HF-SSB equipment installed, given in AEROSPATIALE AS 332 Service Bulletin n° 23-05.

---

Cf. : AEROSPATIALE AS 332 S.B. n° 23-05

---

EFFECTIVE DATE : SEPTEMBER 16, 1989

Sept. 06, 1989

AEROSPATIALE AS 332 helicopters

Ref. : 89-135-037(B)