

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 89-136-059(B)
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE SA 330 (PUMA) helicopters

HF-SSB wire antenna

This Airworthiness Directive applies to all SA 330 helicopters (all versions) equipped with the HF-SSB installation.

With a view to ensuring the safety of all aircraft fitted with this installation, the following measures are rendered mandatory from the effectivity date of this Airworthiness Directive :

- within the next 50 flying hours, bind the double swivels and the antenna retaining wire, as described in the appendix corresponding to the type of HF-SSB equipment installed, given in AEROSPATIALE SA 330 Service Bulletin n° 23-11.

Cf. : AEROSPATIALE SA 330 S.B. n° 23-11

EFFECTIVE DATE : SEPTEMBER 16, 1989

Sept. 06, 1989

AEROSPATIALE
SA 330 (PUMA) helicopters

Ref. : 89-136-059(B)