BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

> Translation of 'Consigne de Navigabilité' Réf.: 89-164-047(B)R1

In case of any difficulty, reference should

be made to the French original issue.

AEROSPATIALE ALOUETTE II helicopters all types

Main Rotor Blades Service-Life limit

The present Airworthiness Directive applies to AEROSPATIALE SE 3130, SE 313 B, SA 3180, SA 318 B and C helicopters equipped with main rotor blades P/N 3130S.11.30.000, serial numbers 13846 to 13949 inclusive without the AMS AEROSPATIALE 07 2257.

Subsequent to the discovery of a fatigue problem at the blade spar/fitting assembly, which could lead to loss of the blade, the service-life limit of the blades identified above is reduced to 400 hours. From the effective date of this Airworthiness Directive :

- 1 blades which have logged more than 375 hours, must be removed from service within the next 25 flying hours.
- 2 blades which have logged less than 375 hours must be removed from service before they reach 400 flying hours.

The present Revision 1 cancels and replaces the original AD 89-164-047(B) of October 18, 1989

EFFECTIVE DATE : OCTOBER 28, 1989 (date of original AD)

April 18, 90	AEROSPATIALE ALOUETTE II helicopters (all types)	89-164-047(B)R1
--------------	---	-----------------