

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 89-198-004(B) R1  
In case of any difficulty, reference should be made to the French original issue.

## AIRBUS INDUSTRIE

### A320 aircraft

Stand-by generator control unit (GCU)

The present Airworthiness Directive applies to AIRBUS INDUSTRIE A320, all models, without modification AIRBUS INDUSTRIE 21052 embodied, or without AIRBUS INDUSTRIE Service Bulletin A320-24-1022 and AIRBUS INDUSTRIE modification 21736, or without AIRBUS Service Bulletin A320-24-1035.

In order to prevent an incorrect in-service functioning of the stand-by GCU, the following measure is rendered mandatory :

- Unless already carried out and before May 31, 1990, replace stand-by GCU :
  - For P/N 520738 by a GCU P/N 520915 according to instructions given by Service Bulletins AIRBUS INDUSTRIE A320-24-1022 and A320-24-1035.
  - For P/N 520754 by a GCU P/N 520915 according to instructions given by Service Bulletin AIRBUS INDUSTRIE A320-24-1035.

Ref. : SB AIRBUS INDUSTRIE A320-24-1022  
SB AIRBUS INDUSTRIE A320-24-1035

This revision 1 cancels and replaces the original AD 89-198-004(B) dated December 27, 1989.

**EFFECTIVE DATE : JUNE 6, 1992**

e/C

May 27, 1992

AIRBUS INDUSTRIE  
A320 aircraft

89-198-004(B) R1