

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 90-030-028(B)R1

In case of any difficulty, reference should be made to the French original issue.

ATR 42-300 and -320 aircraft

Propeller brake

The present Airworthiness Directive applies to ATR 42-300 and -320 aircraft serial numbers 003 to 151 inclusive.

In order to prevent incorrect functioning of the propeller brake, the following measures are rendered mandatory :

- 1/ Before March 01, 1991 install propeller brakes at stage 6 Part number 3037785 as per instructions of Service Bulletin ATR 42-61-0022 rev.2.
- 2/ Before March 01, 1991 improve the propeller brake control system by embodying Service Bulletin ATR 42-61-0005 rev.5 and ATR 42-61-0023 rev.3.

Ref. : Service Bulletin
ATR 42-61-0005 rev. 5
ATR 42-61-0022 rev. 2
ATR 42-61-0023 rev. 3

The present revision 1 cancels and replaces the original AD 90-030-028(B) dated February 21, 1990

EFFECTIVE DATE : MARCH 03, 1990
(same as the original AD)

January 23, 91

ATR 42-300 and -320 aircraft

90-030-028(B)R1