

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 90-155-030(B)R1

In case of any difficulty, reference should be made to the French original issue.

ATR 42 aircraft

Emergency oxygen system for the cabin attendants

This Airworthiness Directive applies to all types and all serial numbers of ATR 42 aircraft.

A/ In order to set the aircraft in compliance with regulation JAR 25-1439 (b)(3) and thus allow communication between the flight compartment and the hostess, when she has put on her oxygen mask, the following measures are made mandatory :

- By May 1st, 1992, install a hood for the attendant situated aft of the cabin, following the application conditions of paragraph 2.C part A of BS ATR 42-35-008 (Mod.2718).

B/ Any alternative solution setting the aircraft in compliance with regulation JAR-25-1439 (b) (3) can be adopted after approval by the Authorities.

The present revision 1 cancels and replaces the AD 90-155-030(B) of September 5, 90

Ref. : Service Bulletin ATR 42-35-008

EFFECTIVE DATE : OCTOBER 1st, 1990

(same as the original AD)

November 27, 91

ATR 42 aircraft

90-155-030(B)R1