

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 91-036-066(B)

In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE SA 330 helicopters

"Jolliet" emergency locator transmitter antenna

The present Airworthiness Directive applies to AEROSPATIALE SA 330 helicopters, versions F, G and J fitted with the JOLLIET emergency locator transmitter antenna P/N JE2-1978-5 (704A35.332.010).

In order to prevent any risk of the loss of the "Jolliet" emergency locator transmitter antenna in flight, while improving its vibration response, the following measures, which form the subject of AEROSPATIALE SA 330 Service Bulletin n° 23.13 are rendered mandatory.

- Within the next 100 flying hours and before May 1, 1991 at the latest, perform the modification (sheathing and bracing the antenna) as per AEROSPATIALE SA 330 S.B. n° 23.13.

Cf. AEROSPATIALE SA 330 S.B. n° 23-13

EFFECTIVE DATE : MARCH 2, 1991

February 20, 91

AEROSPATIALE SA 330
helicopters

91-036-066(B)