

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 91-153-018(B)  
In case of any difficulty, reference should be made to the French original issue.

## AIRBUS INDUSTRIE

### A320aircraft

Overwing escape slide

This Airworthiness Directive applies to A320 AIRBUS INDUSTRIE aircraft, all models, manufacturer serial numbers 002 to 162, 167, 171 to 174.

In order to prevent any possible risk of overwing emergency escape slide right hand and left hand deployment failure, the following is rendered mandatory :

- At next scheduled maintenance check or within 50 flight hours after effective date of this Airworthiness Directive, carry out an inspection of the right hand and left hand overwing slide flexible control cable to check the connections with inflation bottle actuating cables as per AIRBUS INDUSTRIE All Operators Telex Ref. : AOT 25-02 dated May 16, 1991.

No further action is required after accomplishment of this Airworthiness Directive or AOT 25-02 dated May 16, 1991.

Ref. : AIRBUS INDUSTRIE All Operators Telex 25-02 dated May 16, 1991  
or any later revision.

**EFFECTIVE DATE : JULY 20, 1991**

e/C

July 10, 1991

AIRBUS INDUSTRIE  
A320 aircraft

91-153-018(B)