

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 91-202-050(B)

In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE ALOUETTE III helicopters

Electric hoist installation

This Airworthiness Directive concerns AEROSPATIALE ALOUETTE III helicopters, types 316B, 316C, 3160 and 319B equipped with the LUCAS AIR EQUIPEMENT electric hoist, part number :

76370
76370-010
76370-011
76370-020
76370-030

Subsequent to an untimely triggering of the hoist pyrotechnic cartridge in service, the following measures are rendered mandatory :

- 1/ Within the 50 flying hours following receipt of this Airworthiness Directive, and at the latest before October 1, 1991, apply Service-Bulletin AEROSPATIALE ALOUETTE III 316-319 N° 25.61 in its entirety.
- 2/ At every T inspection or every 12 months (the first of the two limits reached is to be applied) and similarly each time the hoist or hoist arm is removed, for aircraft modified as per paragraph 1C of Service-Bulletin ALOUETTE III 316-319 N° 25.61 :
 - check the resistance as per paragraph 1C (3) of Service-Bulletin ALOUETTE III 316-319 N° 25.61.

Ref. : SB AEROSPATIALE ALOUETTE III 316-319 N° 25.61

EFFECTIVE DATE : UPON RECEIPT

September 18, 91

AEROSPATIALE ALOUETTE III
helicopters

91-202-050(B)