

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 91-203-035(B)

In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE SA 341 - 342 GAZELLE helicopters

Electric hoist installation

This Airworthiness Directive concerns AEROSPATIALE SA 341 G - 342 J helicopters equipped with the LUCAS AIR EQUIPEMENT electric hoist (unmodified 07.2516), part number :

76370
76370-010
76370-011
76370-020
76370-030

Subsequent to an untimely triggering of the hoist pyrotechnic cartridge in service, the following measures are rendered mandatory :

- 1/ Within the 50 flying hours following receipt of this Airworthiness Directive, and at the latest before October 1, 1991, apply Service-Bulletin AEROSPATIALE SA 341 - 342 N° 25.05 in its entirety.
- 2/ At every T inspection or every 24 months (the first of the two limits reached is to be applied) and similarly each time the hoist or hoist arm is removed, for aircraft modified as per paragraph 1C of Service-Bulletin AEROSPATIALE N° 25.05 :
 - check the resistance as per paragraph 1C (2) of Service-Bulletin N° 25.05.

Ref. : SB AEROSPATIALE SA 341 - 342 N° 25.05

EFFECTIVE DATE : UPON RECEIPT

September 18, 91

AEROSPATIALE SA 341 - 342 GAZELLE
helicopters

91-203-035(B)