

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 91-237-044(B)

In case of any difficulty, reference should be made to the French original issue.

ATR 42 aircraft series 200 and 300

Auto pilot

The present Airworthiness Directive concerns ATR 42 series 200 and 300, on which modifications 3112 and 3169 have not been embodied.

In order to improve roll out-of-trim indications and eliminate any risk of roll trim command which would accentuate the out-of-trim, the following actions are made mandatory :

- By October 31, 1993, replace the HONEYWELL auto pilot P/N 7003974-604 by a HONEYWELL auto pilot P/N 7003974-605 and modify its wiring according to SB's ATR-42-22-0015 and ATR 42-27-0058.
- Amend AFM accordingly.

Ref. : SB ATR 42-22-0015
SB ATR 42-27-0058

EFFECTIVE DATE : NOVEMBER 9, 1991

October 30, 1991

ATR 42 aircraft series 200 and 300

91-237-044(B)