

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 91-238-009(B)

In case of any difficulty, reference should be made to the French original issue.

ATR 72 aircraft series 100 and 200

Auto pilot

The present Airworthiness Directive concerns the ATR 72 series 100 and 200, on which modifications 3112 and 3168 have not been embodied.

In order to eliminate any risk of roll trim command which would accentuate the out-of-trim, the following actions are made mandatory :

- By October 31, 1993, replace the HONEYWELL auto pilot P/N 7003974-603 by a HONEYWELL auto pilot P/N 7003974-606 and modify its wiring according to SB's ATR 72-22-1004 and ATR 72-27-1019.

- Amend AFM accordingly.

Ref. : SB ATR 72-22-1004
SB ATR 72-27-1019

EFFECTIVE DATE : NOVEMBER 9, 1991

October 30, 1991

ATR 72 aircraft series 100 and 200

91-238-009(B)