

BUREAU VERITAS

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive*

Translation of 'Consigne de Navigabilité'

Réf.: 91-250-067(B)

In case of any difficulty, reference should be made to the French original issue.

## AEROSPATIALE SA 330 helicopters

### Hydraulic system

The present Airworthiness Directive applies to AEROSPATIALE SA 330 helicopters, versions F, G and J on which the MGB has been overhauled or repaired at Marignane between February 1987 and August 1991.

Further to a report of contamination of the hydraulic system, the following measures are rendered mandatory :

- For MGBs installed on aircraft (unless this has already been done) : Within the next 50 flying hours after the effective date of this Airworthiness Directive.
- For MGBs not installed on aircraft : Before they are installed.

Check the main servocontrol filters as per AEROSPATIALE Telex Service n° 01.48.

Ref. : SA 330 Telex Service n° 01.48

EFFECTIVE DATE : DECEMBER 07, 1991

November 27, 91

AEROSPATIALE SA 330 helicopters

91-250-067(B)