BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité' Réf.: 91-260-018(B)

In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE SN 601 "CORVETTE" airplanes

Air conditioning system

The present Airworthiness Directive applies to AEROSPATIALE SN 601 aircraft all serial numbers.

In order to ensure the integrity of all hot air distribution ducting comprised between the primary heat exchanger and the water separator, the following inspection is rendered mandatory:

1/ Inspection (according to SB N° 21-6)

All ducting must be checked in accordance with paragraph C(2) "Inspection method", SB 21-6 by the effective date of this Airworthiness Directive.

2/ Inspection findings

Operators are requested to implement the procedure called for in paragraph E, "Inspection findings" in SB 21-6, in order to evolve subsequent maintenance tasks.

Ref. : AEROSPATIALE SB N° 21-6

EFFECTIVE DATE: DECEMBER 21, 1991

December 11, 91 AEROSPATIALE SN 601 "CORVETTE" 91-260-018(B) airplanes