

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 92-011-036(B)R1

In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER
SA 341-342 helicopters

Intermediate gearbox attachment

This Airworthiness Directive applies to SA 341G and SA 342J helicopters equipped with an intermediate gearbox (I.G.B) not modified to AMS 341A07.1636.

To prevent wear of the front attachment tab, that might result in loss of the intermediate gearbox, the following measures are made mandatory :

- Once during the next inspection after the last flight of the day then,
- At each removal or installation of the I.G.B.

Comply with paragraph 1C of EUROCOPTER Service Bulletin SA 341-342 n° 65-43 R1.

Ref. : EUROCOPTER S.B. SA 341-342 n° 65-43 R1

The present Revision 1 supersedes AD 92-011-036(B) dated January 08, 1992

EFFECTIVE DATES :

ORIGINAL AD : JANUARY 18, 1992
REVISION 1 : MAY 09, 1992

April 29,1992

EUROCOPTER
helicopters SA 341-342

92-011-036(B)R1