

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 1994-085(AB) R2
In case of any difficulty, reference should be made to the French original issue.

SICMA AERO SEAT

Passenger seats

Aft track fittings (ATA 25)

The present Airworthiness Directive applies to all SICMA AERO SEAT passenger seats equipped with SICMA aft track fittings P/N 90-000120-790-0, to be mounted on aircraft seat track.

The following part number seats are among concerned seats :

P/N	4201-series	4203-series	
	4204-series	4205-series	
P/N	5505-series	5006-series	
	5010-series	5011-series	
	5014-series		
P/N	6343-series	6347-series	
P/N	6503-series	6506-series	6514-series
	6518-series	6523-series	6525-series
	6526-series	6528-series	6529-series
	6531-series	6532-series	6534-series
	6535-series	6536-series	6538-series
	6541-series	6542-series	
P/N	7147-series	7158-series	
	7809-series		
P/N	8301-series	8302-series	
	8503-series	8504-series	8506-series
P/N	9007-series	9011-series	9012-series
	9018-series	9019-series	9032-series
P/N	9101-series	9102-series	9103-series
	9105-series	9106-series	9108-series
	9109-series	9111-series	9114-series
	9118-series	9119-series	9121-series
	9128-series	9133-series	9134-series
	9135-series	9136-series	9139-series
	9140-series	9141-series	9143-series
	9144-series	9156-series	9157-series
	9160-series	9162-series	9165-series
P/N	9202-series	9206-series	
	9210-series	9211-series	

n/GH

.../...

July 13, 1999

SICMA AERO SEAT
Passenger seats

1994-085(AB) R2

The detailed P/N list of concerned seats is given by annex 1 of Service Bulletin SICMA AERO SEAT 90-25-005R1 (or any further approved revision).

As some cases of aft track fitting P/N 90-000120-790-0 becoming loose have been noticed in service, the following instructions are rendered mandatory at the effective date of the present Airworthiness.

1. a) Before accomplishment of 600 flight hours after 23 April 1994 and then at intervals not to exceed 600 flight hours check the locking of the aft track fittings P/N 90-000120-790-0 by following the instructions given in SICMA AERO SEAT Alert Service Bulletin A 90-25-002 Revision A dated February 04, 1993.
- b) Before September 30, 1994, modify the aft track fitting P/N 90-000120-790-0 by accomplishment of technical instructions given by the SICMA AERO SEAT Service Bulletin : 90-25-005 R1 (or any further approved revision).

Stamp accomplishment of modification on identification plate of the seats (ref. to pages 4 and 7 of Service Bulletin).

- c) After September 30, 1994, non modified aft track fittings as spares is no more allowed.

Note 1 : After modification of aft track fitting P/N 90-000120-790-0 becomes P/N 90-000123-790-0.

Note 2 : Accomplishment of one of the following SICMA AERO SEAT Service Bulletins :

42-25-001	50-25-001	63-25-004	65-25-001
71-25-012	78-25-001	85-25-001	91-25-001
83-25-001	92-25-001	93-25-001	90-25-004

is equivalent to accomplishment of Service Bulletin SICMA AERO SEAT 90-25-005R1. These Service Bulletins have the same technical instructions. The only differences are serial numbers of seats and associated operators.

- 2) As per revision 2 of Service Bulletin SICMA AERO SEAT 90-25-005, tab locks P/N 00-4399 must be discarded after each seat removal. New ones must be installed at each new seat installation.
- 3) Accomplishment of service bulletin SICMA AERO SEAT 90-25-009 is an alternative mean of compliance to this airworthiness directive. Tab locks P/N 00-4399 are not used when accomplishing service bulletin SICMA AERO SEAT 90-25-009. Therefore, in this case, paragraph 2 of this Airworthiness Directive is not applicable.

REF. : Alert Service Bulletin SICMA AERO SEAT A90-25-002

Rev. A dated February 04, 1993.

Service Bulletin SICMA AERO SEAT 90-25-005R1 and its annex

Service Bulletins SICMA AERO SEAT 42-25-001, 50-25-001, 63-25-004, 65-25-001, 71-25-012, 78-25-001, 85-25-001, 91-25-001, 83-25-001, 92-25-001, 90-25-004, 90-25-009.

The present Revision 2 replaces AD 94-085(B) R1 dated June 22, 1994.

EFFECTIVE DATES :

Original issue	: APRIL 23, 1994
Revision 1	: JULY 02, 1994
Revision 2	: JULY 23, 1999