

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 94-087-068(B)
In case of any difficulty, reference should be made to the French original issue.**

EUROCOPTER FRANCE

AS 350 helicopters

MGB Oil Pressure Switch

The present Airworthiness Directive applies to AS 350 B, BA, D, B1 and B2 helicopters fitted with MGB oil pressure switch P/N 704A37.721.082 (S 1130.021.082).

Since possible malfunction of the pressure switch has been evidenced at the works, the following measures are rendered mandatory :

- Remove the above mentioned pressure switches before June 01, 1994 at the latest.
From this same date, the installation of these switches is prohibited.

REF. : EUROCOPTER FRANCE AS 350 Telex Service N° 01-43

EFFECTIVE DATE : ON RECEIPT

n/W

April 13, 1994

EUROCOPTER FRANCE
AS 350 helicopters

94-087-068(B)