

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 94-145-039(B)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER FRANCE

SA 365 C helicopters

Free Wheel

The present Airworthiness Directive concerns SA 365 versions C, C1, C2 and C3 helicopters equipped with free wheel P/No 365A35.1004.00.

Subsequent to an incident which occurred during the rotor off phase on a free wheel found without oil, the following measures are rendered mandatory.

Comply with paragraph BB of EUROCOPTER FRANCE 365 C Telex Service No 01.32 :

1. Within the 100 flying hours from the effective date of this Airworthiness Directive.

Note : If the seal holder has to be replaced in accordance with paragraph B.B.2 of the Telex Service, the replacement can be carried out within a period of 50 flying hours after compliance with paragraph B.B.

2. Before installing on the helicopter a new or an overhauled free wheel held as spares.

REF. : EUROCOPTER FRANCE SA 365 C Telex Service No 01-32

EFFECTIVE DATE : ON RECEIPT

n/W

June 22, 1994

EUROCOPTER FRANCE
SA 365 C helicopters

94-145-039(B)