AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 94-162-056(B)

In case of any difficulty, reference should be made to the French original issue.

ATR

ATR 42 aircraft

Karman fairings attachment clips

This Airworthiness Directive applies to ATR 42 aircraft series 200 and 300 on which modification 2601 (or Service Bulletin ATR 42-53-0063) has been embodied and on which modification 3942 or Service Bulletin ATR 42-53-0081 (Mod 3941) has not been embodied.

In order to avoid a possible deformation of the fairings clips at level of wing front and rear spars upper flange attachment, and of the engine nacelle upper cowls clips, the following directives become mandatory at the effective date of this Airworthiness Directive:

- Before December 31, 1995, modify the concerned clips following the directives of Service Bulletin ATR 42-53-0081.

REF.: Service Bulletin ATR 42-53-0063 Service Bulletin ATR 42-53-0081

OCIVICE Buildin ATT 42 90 0001

EFFECTIVE DATE: JULY 16, 1994

n/F

July 06, 1994 A T R ATR 72 aircraft 94-162-056(B)