

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 95-089-010(B)
In case of any difficulty, reference should be made to the French original issue.**

AIRBUS INDUSTRIE

A330 Aircraft

Deactivation of the avionics ground refrigeration unit (G R U)

This Airworthiness Directive applies to AIRBUS INDUSTRIE A330 aircraft all models fitted with the avionics Ground Refrigeration Unit (AIRBUS INDUSTRIE modification 40063) and having not received AIRBUS INDUSTRIE modifications 43582 and 43583 or AIRBUS INDUSTRIE Service Bulletin A330-21-3028.

In order to prevent ventilation of the ADIRUs by airflow with a high level of humidity which could result in water contamination leading to multiple ADIRU failures, the following measures are rendered mandatory on the effective date of this Airworthiness Directive :

- Within 500 flight hours on the effective date of this Airworthiness Directive, unless already accomplished, perform the deactivation of the avionics Ground Refrigeration Unit in accordance with the instructions given in the paragraph 4 of the AIRBUS INDUSTRIE All Operator Telex A330/A340 AOT 21-01 dated March 28, 1995.

Accomplishment of AIRBUS INDUSTRIE Service Bulletin A330-21-3028 cancels the requirements of this Airworthiness Directive.

Ref. : AIRBUS INDUSTRIE A.O.T.A330/A340 AOT 21-01 dated March 28, 1995
Service Bulletin A330-21-3028

EFFECTIVE DATE : JUNE 03, 1995

v/JYR

May 24, 1995

AIRBUS INDUSTRIE
A330 Aircraft

95-089-010(B)