

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 96-007-073(B)
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A320 Aircraft

Smoke detection in lavatories
Modification of the air extraction duct grilles

This Airworthiness Directive applies to AIRBUS INDUSTRIE A320 aircraft, all models, without AIRBUS INDUSTRIE modification 22561 or without AIRBUS INDUSTRIE Service Bulletin A320-26-1017 (installation of an ambient system or without modification 24548 or without AIRBUS INDUSTRIE Service Bulletin A320-26-1037

In order to void incorrect installation of the lavatory air extraction duct grill, which could reduce the performance of the smoke detection system, the following measures are rendered mandatory on the effective date of this Airworthiness Directive :

- Within 500 flight hours, unless already accomplished, modify on each lavatory, the air extraction duct grill in accordance with the instructions of AIRBUS INDUSTRIE Service Bulletin A320-26-1037.

Note : The application of this Airworthiness Directive cancels the requirements of Airworthiness Directive 94-168-058(B).

REF. : AIRBUS INDUSTRIE Service Bulletin A320-26-1017
AIRBUS INDUSTRIE Service Bulletin A320-26-1037
(or any further approved revisions)

EFFECTIVE DATE : JANUARY 13, 1996