

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 96-109-063(B)
In case of any difficulty, reference should be made to the French original issue.

ATR

ATR 42 aircraft

Engine nacelle drain system

This Airworthiness Directive applies to ATR 42 aircraft models 300 and 320 on which ATR modification N° 1696 or associated Service Bulletin ATR 42-71-0010 has not been embodied.

To prevent the consequences of a fuel leak at the nozzles, which could lead to an accumulation of fuel in the engine nacelle, likely to generate a fire, and in addition to the measures that will be taken for the engine, the following measure is made mandatory on the date of enforcement of this Airworthiness Directive :

- Before 1st May 1998, embody the engine drain system modification in compliance with the instructions provided by Service Bulletin ATR 42-71-0010.

REF. : Service Bulletin ATR 42-71-0010

EFFECTIVE DATE : JUNE 15, 1996

v/JPD

June 05, 1996

ATR
ATR 42 aircraft

96-109-063(B)