

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 97-134(AB)  
In case of any difficulty, reference should be made to the French original issue.

## SICMA AERO SEAT

### Passenger seats

Leg collars

#### 1) Involved parts

This Airworthiness Directive is applicable to all SICMA AERO SEAT seats whose P/N and S/N are shown in the following table and which are equipped with leg collars P N 95-000100-008-0 :

SEAT P/N	SEAT S/N	SEAT P/N	SEAT S/N	SEAT P/N	SEAT S/N
5036211-01	7 & 8	91A1300-02	2	9612201-14	1
5036201-02	7 & 8	91A1310-03	7 & 8	9612210-31	1
5036211-03	4	91A1300-04	8 & 9	9612200-32	1
5036201-04	4	91A1310-05	3	5038211-01	69 to 81
5036241-05	10 to 12	91A1300-06	3	5038201-02	70 to 82
6573211-01	7 & 8	91A1310-07	2	5038241-03	79 to 85
6573201-02	7 & 8	91A1300-08	2	5038211-07	1
6573211-03	17 to 20	91A1310-09	2	5038201-08	1
6573201-04	17 to 20	91A1310-11	2	5044211-01	13
6573211-05	4	9611210-01	11 to 20	5044201-02	13
6573201-06	4	9611200-02	9 to 16	5044241-03	13
6573341-07	7 & 8	9611211-03	2	6573211-11	2
9184210-15	9 & 10	9611201-04	2	6573211-12	2
9184200-16	9 & 10	9611200-06	2	5673211-13	2
9184210-17	5	9611210-11	2	5673211-14	2
9184200-18	5	9611200-16	2	5673211-15	2
9184440-20	96 to 124	9612210-21	1 to 16	5673211-16	2
9184440-21	9 to 10	9612200-22	1 to 15		
91A1310-01	2	9612211-13	1		

#### 2) Reason for the Airworthiness Directive

Avoid any risk of structural weakness due to a temporary change of a surface protection.

... / ...

**3) Action and limit of completion**

Replace the leg collars as described in the Service Bulletin SICMA AERO SEAT N° 95-25-003 before July 31, 1997.

---

Ref. : Service Bulletin SICMA AERO SEAT  
N° 95-25-003

---

**EFFECTIVE DATE : JUNE 28, 1997**