

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 97-159-071(B)
In case of any difficulty, reference should be made to the French original issue.**

ATR

ATR 42 Aircraft

Karman fairing panel fasteners

1 - INVOLVED MATERIAL :

All ATR 42 aircraft models 200, 300 and 320 on which ATR modification N° 2601 (Service Bulletin ATR 42-53-0063) or ATR modification N° 3942 have not been embodied.

2 - ACTIONS :

In order to avoid severe in-flight vibrations induced by a loosening of wing to fuselage fairing panels attachments, consequence of an incorrect installation of these panels, the following measures are rendered mandatory :

- replace the panel attachments in accordance with the instructions described in Service Bulletin ATR 42-53-0082.

3 - COMPLIANCE TIME :

At the first opportunity or at latest before March 31, 1998.

4 - REFERENCES :

- Service Bulletin ATR 42-53-0063 or any further approved revision.
- Service Bulletin ATR 42-53-0082 or any further approved revision.

EFFECTIVE DATE : JULY 26, 1997