GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref.: 2000-235-045(A) In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

SA 365 C helicopters

Main rotor blades - Service life limitations (ATA 01, 62)

1. **EFFECTIVITY**:

SA 365 helicopters, versions: C, C1, C2 and C3 fitted with main rotor blade part numbers:

- 365A 11.0010.03
- 365A 11.0020.02 and 03.

2. REASON:

This Airworthiness Directive is issued to inform operators of the new Service Life Limits of main rotor blades, P/N 365A 11.0010.03 and P/Nos. 365A 11.0020.02 and .03.

3. MANDATORY ACTIONS AND COMPLIANCE TIME:

The following limitations are rendered mandatory from the effective date of this Airworthiness Directive:

- 3.1. The service life limit of main rotor blades, P/N 365A 11.0010.03 is set to 10 000 operating hours.
- **3.2.** The service life limit of main rotor blades, P/Nos. 365A 11.0020.02 and .03 is set to 12 000 operating hours.

REF.: EUROCOPTER SA 365 C Master Servicing Recommendations (PRE), Rush Revision No. 29b date-Code 00.22

EFFECTIVE DATE:

On receipt from JUNE 14, 2000

n/DJ

June 14, 2000	EUROCOPTER SA 365 C Helicopters	2000-235-045(A)
---------------	------------------------------------	-----------------