

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-044-083(B)
In case of any difficulty, reference should be made to the French original issue.

EADS ATR

ATR 42 aircraft

Deicing - Revision of Aircraft Flight Manual (ATA 04, 30)

1. APPLICABILITY:

ATR 42 aircraft models -200 /-300 /-320 /-400 /-500.

2. REASON:

The purpose of this Airworthiness Directive (AD) is to modify the Aircraft Flight Manual so that the crew activate the wing and tail deicing system as soon as ice accretion is detected on the aircraft, and as long as this later is not exited from icing conditions.

This AD takes into account the requirements of FAA AD 99-19-10.

3. ACTIONS:

Within 15 days after the effective date of this AD, revise the approved Aircraft Flight Manual by incorporating the following modification. This may be accomplished by inserting a copy of this AD in the Aircraft Flight Manual.

- In chapter Normal Procedures - Icing conditions:

Replace the sentence "At first visual indication of ice accretion and as long as ice builds up on the airframe, the following procedure must be applied." by "At first visual indication of ice accretion and as long as atmospheric icing conditions exist, the following procedure must be applied."

Note: The following AFM's comply with the requirements of this AD:

- ATR42-200, -300, -320 models: TR (Temporary Revision) No. 41 dated October 2000,
- ATR42-400, -500 models: RN (Normal Revision) No. 5 dated May 2000.

REF. : Approved Aircraft Flight Manual.
AD FAA 99-19-10.

EFFECTIVE DATE : FEBRUARY 03, 2001

n/GH

January 24, 2001

EADS ATR
ATR 42 aircraft

2001-044-083(B)