

# CONSIGNE DE NAVIGABILITE

définie par la DIRECTION GENERALE DE L'AVIATION CIVILE

*Les examens ou modifications décrits ci-dessous sont impératifs. La non application des exigences contenues dans cette consigne entraîne l'inaptitude au vol de l'aéronef concerné.*

## DASSAULT AVIATION

### Avions Mystère Falcon 900/Falcon 900EX

Aménagement (ATA 25)

#### 1. APPLICABILITE :

La présente Consigne de Navigabilité (CN) concerne les avions Mystère Falcon 900 numéros de série 184 à 187 inclus et les avions Falcon 900EX numéros série 28 et 65 à 85 inclus, qui n'ont pas la modification DASSAULT AVIATION M3424 (ou les Bulletins Service DASSAULT AVIATION (BS) F900EX-SB109/F900-SB220) appliqués.

#### 2. RAISONS :

Lors de recherches d'amélioration de l'insonorisation cabine, il est apparu que, dans certaines situations, les revêtements d'insonorisation situés derrière les flancs de banquette en cabine ne répondaient pas aux exigences applicables de résistance au feu.

Cette situation, si non corrigée, pourrait entraîner une réduction de la protection au feu en cas de début d'incendie en cabine.

#### 3. ACTIONS :

Dans les 7 mois à compter de la date d'entrée en vigueur de cette CN, remplacer les revêtements concernés conformément aux instructions du Bulletin Service F900-220 ou F 900EX-109.

---

REF. : BS DASSAULT AVIATION : MF900-220 ou F900EX-109, édition originale  
Toute révision ultérieure approuvée de ces BS est acceptable.

---

**DATE D'ENTREE EN VIGUEUR : 07 JUILLET 2001**

n/GH

Date : 27/06/2001

**DASSAULT AVIATION**  
**Avions Mystère Falcon 900/Falcon 900EX**

**2001-267-035(B)**

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 2001-267-035(B)  
In case of any difficulty, reference should be made to the French original issue.

## DASSAULT AVIATION

### Mystère Falcon 900/Falcon 900EX aircraft

Layout (ATA 25)

#### 1. APPLICABILITY:

Mystère Falcon 900 aircraft serial numbers 184 to 187 inclusive, Falcon 900EX serial numbers 28 and 65 to 85 inclusive, on which DASSAULT AVIATION modification M3424 (or DASSAULT AVIATION Service Bulletin (SB) MF900-220 / F900EX-109 have not been embodied.

#### 2. REASONS:

While researching to improve cabin soundproofing material, a situation where a new soundproofing material assembly type not withstanding fire resistant applicable requirements appeared.

This situation, if not corrected, could result in reduced fire protection in case of fire beginning in the cabin.

#### 3. ACTIONS:

Within seven month since effective date of this Airworthiness Directive, replace the concerned soundproofing materials in accordance with instructions of SB F900-220 or F900EX-109.

\_\_\_\_\_  
REF.: SB DASSAULT AVIATION MF900-220 or F900EX 109, original issue  
Any later approved revision of these SB's is acceptable.  
\_\_\_\_\_

**EFFECTIVE DATE : JULY 07, 2001**