

M.A.L.

MEDEDELINGEN
AAN NEDERLANDSE
LUCHTVARENDEN
EN EIGENAREN VAN
LUCHTVAARTUIGEN)

NEDERLAND

RIJKSLUCHTVAARTDIENST
LUCHTVAARTINLICHTINGDIENST

134/71

2 dec

(AIR 607)

PLESMANWEG 1—6 'S-GRAVENHAGE, TELEFOON 070 - 62 43 21 (T. 2124 - 2125 - 2126)

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt het hoofd van de afdeling Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.

71-84-57

Fokker F.28

- Betreft** : Flight control surfaces - balancing of
Subject : aileron servo tabs.
- Van toepassing op** : F.28 Aircraft Serial Numbers
Applies to : 11003 to 11038 inclusive, 11040,
11991 to 11994 inclusive.
- Tijdstip van uitvoering** : Required before December 15, 1971.
Compliance
- Datum van inwerkingtreding** : December 2, 1971.
Effective date
- Uitvoering** : In accordance with Fokker Service
Accomplishment : Bulletin F.28/57-33, dated December
2, 1971 or later R.L.D. approved
revision.

All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Department of Civil Aviation
Aeronautical Inspection Division
P.O.Box 7555
Schiphol Airport - East
The Netherlands.