

M . A . L .

(Mededelingen
aan nederlandse
luchtvaardigen
en eigenaren van
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST
LUCHTVAARTINLICHTINGDIENST

4/72

8 jan

(AIR 619)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 62 43 21 (T. 2124 - 2125 - 2126)

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING

(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt het hoofd van de afdeling Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Division of the Department of Civil Aviation prescribes hereby the following Airworthiness Directive.

72-04-27

Fokker F.28

- Betreft** : Horizontal stabilizer control system -
Subject : input mechanism - modification of
springbox sticking switch operating
mechanism.
- Van toepassing op** : F.28 Aircraft Serial Numbers 11003 to
Applies to 11016 inclusive.
- Tijdstip van uitvoering** : Required before August 1, 1972.
Compliance
- Datum van inwerkingtreding** : January 8, 1972.
Effective date
- Uitvoering** : In accordance with Fokker Service
Accomplishment Bulletin F.28/27-28 dated November
22, 1971 incl. revision 1, dated January
6, 1972, or later R.L.D. approved
revision.

All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Department of Civil Aviation
Aeronautical Inspection Division
P.O.Box 7555
Schiphol Airport - East
The Netherlands.