

M . A . L .

(Mededelingen
aan nederlandse
luchtvaardigen
en eigenaren van
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST
LUCHTVAARTINLICHTINGDIENST

37/74

15 May

(AIR 832)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Directorate of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

74-20-52

Fokker F.28

Betreft: Passenger door - modification of door
Subject: locking mechanism and introduction of
new switch brackets.

Van toepassing op: F.28 Aircraft, serial numbers:
Applies to: 11003 to 11064 inclusive, 11991 to
11993 inclusive.

Tijdstip van uitvoering: Required before 1st October 1974.
Compliance:

Datum van inwerkingtreding: May 15, 1974.
Effective Date:

Uitvoering: In accordance with Part IV of Fokker
Accomplishment: Service Bulletin F.28/52-43 dated April
16, 1974, or later R.L.D. approved revision.

All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O. Box 7555, Telex 15267 lispl nl
Schiphol Airport - East
The Netherlands