

**B.L.A.**

**Ministerie van Verkeer en Waterstaat**

**RIJKSLUCHTVAARTDIENST**

**LUCHTVAARTINSPECTIE**

**A87/75**

**26 sep**

Schiphol-Oost - Gebouw 144 - Stationsplein - Postbus 7555 - Telefoon 020 5169111

---

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING  
(BLA)**

**NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) en BLA nr. 74-70-00 (MAL nr. 112/74) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.*

**75-72-27**

**FOKKER F.27**

**Betreft:** Aileron control system-inspection and  
**Subject:** rectification of cable drum in control system.

**Van toepassing op:** All F.27 aircraft up to and inclusive  
**Applies to:** aircraft serial number 10522.  
Aircraft serial numbers 10508 and 10510 up to and inclusive 10522 will be inspected and if necessary rectified prior to delivery.

**Tijdstip van uitvoering:** Before 1st January 1976.  
**Compliance:**

**Datum van inwerkingtreding:** 26 september 1975.  
**Effective Date:**

**Uitvoering:** In accordance with Fokker F.27 Service  
**Accomplishment:** Bulletin F.27/27-109 dated 22 August 1975 or later RLD approved revision.

*All operators of the above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.*