

Ministerie van Verkeer en Waterstaat

B.L.A.

RIJKSLUCHTVAARTDIENST

LUCHTVAARTINSPECTIE

A88/75

26 sep

Schiphol-Oost - Gebouw 144 - Stationsplein - Postbus 7555 - Telefoon 020 5169111

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING  
(BLA)  
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) en BLA nr. 74-70-00 (MAL nr. 112/74) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.*

**75-73-27**

**FOKKER F.27**

**Betreft:** Aileron control system-improvement of  
**Subject:** the connection of the rod of the differential sector at wing station 10030 L.H. and R.H.

**Van toepassing op:** All F.27 aircraft up to and inclusive  
**Applies to:** aircraft serial number 10516.

**Tijdstip van uitvoering:** Before 31st December 1975.

**Compliance:**

**Datum van inwerkingtreding:** 26 september 1975.

**Effective Date:**

**Uitvoering:** In accordance with Fokker F.27 Service  
**Accomplishment:** Bulletin F.27/27-110 dated 25 August 1975 or later RLD approved revision.

*All operators of the above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.*

**Note:** Address inquiries regarding this Airworthiness Directive to:  
Civil Aviation Department  
Aeronautical Inspection Directorate  
P.O. Box 7555  
Schiphol Airport - East  
The Netherlands  
Telex: 15267 lispl nl  
Telef: 020 - 5163260