

Ministerie van Verkeer en Waterstaat

B.L.A.

RIJKSLUCHTVAARTDIENST

LUCHTVAARTINSPECTIE

A128/76

12 Nov

Schiphol-Oost - Gebouw 144 - Stationsplein - Postbus 7555 - Telefoon 020 5169111

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)**

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) en BLA nr. 74-70-00 uitg. 3 (MAL nr. 35/76) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive

76-104-27

FOKKER F.27

Betreft: Flight Controls
Subject: Aileron-attachment of deflection limitation stop bolts improved.

Van toepassing op: F.27 Aircraft Serial Numbers:
Applies to: 10408 to 10510 inclusive
Aircraft serial Numbers 10511 and subsequent will have this change incorporated prior to delivery.

Tijdstip van uitvoering: Required before 31 December 1976
Compliance:

Datum van inwerkingtreding: November 12, 1976
Effective date:

Uitvoering: In accordance with Fokker F.27 Service
Accomplishment: Bulletin F.27/27-112 dated 18 October 1976 or later RLD approved revision.

All operators of the above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O. Box 7555
Schiphol Airport - East
The Netherlands
Telex: 15267 rldli nl
Telef.: 020-5163208