

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) en BLA nr. 74-70-00 uitg. 3 (MAL nr. 35/76) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA nr. 77-40-24
FOKKER F.28

Betreft:

Subject:

ELECTRICAL POWER

General - inspection and repair of electrical cables

Van toepassing op:

Applies to:

F.28 aircraft serial numbers:

11003 to 11041 inclusive;

11991 to 11993 inclusive.

Aircraft serial numbers 11042 and up are equipped with a different type of cable, to which the Fokker Service Bulletin F.28/24-29 does not apply.

Reden:

Reason:

To check for possible local damage to electrical cables resulting in deterioration of the insulation by Skydrol attack.

Tijdstip van uitvoering:

Compliance:

Required before 6th June 1977

Datum van inwerkingtreding:

Effective date:

May 24, 1977

Uitvoering:

Accomplishment:

In according with Fokker F.28 Service Bulletin F.28/24-29 dated 6 May 1977 or later R.L.D. approved revision.

All operators of the above mentioned aircraft are receiving the Fokker Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O. Box 7555
Schiphol Airport - East
The Netherlands
Telex: rldli nl 15267
Telef: 020 - 5163280