

Ministerie van Verkeer en Waterstaat
Rijksluchtvaartdienst
Luchtvaartinspectie (publ. Nr. 78/14)

Schiphol-Oost - Gebouw 144 - Stationsplein - Postbus 7555 - Telefoon 020 - 5169111

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 uitg. 3 (publ. nr. A110/77) en BLA nr. 74-70-00 uitg. 3 (MAL nr. 35/76) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA Nr. 78-13-52
FOKKER F. 28

Betreft: DOORS
Subject: Cargo doors - modification of actuating mechanism
of of door lock warning switch.

Van toepassing op: F28 Aircraft serial numbers:

Applies to: 11003 to 11112 inclusive, 11115, 11116, and 11120.
11991 to 11993 inclusive.

NOTE: Fokker Service Bulletin F28/52-80 is not applicable to rear cargo doors of aircraft serial numbers 11003 to 11020 inclusive.

This change will be incorporated, prior to delivery, on aircraft serial numbers 11113, 11114, 11117, 11118, 11119, 11121 and subsequent.

Tijdstip van uitvoering: Required before 1 July 1978.
Compliance:

Datum van inwerkingtreding: 12 January 1978
Effective Date:

Uitvoering: In accordance with Fokker Service Bulletin
Accomplishment: F.28/52-80 dated 28 November 1977
or later RLD approved revision.