

Ministerie van Verkeer en Waterstaat

Rijksluchtvaartdienst

Luchtvaartinspectie (publ. Nr. 79/30)

31 jan.

Schiphol-Oost - Gebouw 144 - Stationsplein - Postbus 7555 - Telefoon 020 - 5169111

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING

(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 uitg. 3 (publ. nr. A110/77) en BLA nr. 74-70-00 uitg. 4 (publ. 78/101) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA nr. 79-27-24

FOKKER F. 27

Betreft: Wiring connection change on the battery reverse
Subject: current circuit breakers.

Van toepassing op: F. 27 aircraft serial numbers 10526, 10527, 10529,
Applies to: 10543, 10547, 10553, 10555, 10556, 10563, 10564,
10565, 10570, 10582 and 10583.

Tijdstip van uitvoering: Required before 31 march, 1979.
Compliance:

Datum van inwerkingtreding: 5 february 1979
Effective Date:

Uitvoering: In accordance with Fokker F.27 Special Instruction
Accomplishment: No. 76 dated 20 november 1978.

All operators of the above mentioned aircraft are receiving this Special Instruction directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O. Box 7555
1117 ZH SCHIPHOL
The Netherlands
Telex: 15267 ridli nl
Telef: 020 - 51632 79