

Ministerie van Verkeer en Waterstaat
Rijksluchtvaartdienst

BLA

Luchtvaartinspectie

(publ. Nr. 83/50)
22 Jul

Schiphol-Oost - Gebouw 144 - Stationsplein - Telefoon 020 - 5169111

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 uitg. 4 en BLA nr. 74-70-00 uitg. 7 maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA Nr. 80-37-55 Iss. 2

FOKKER F.28

Betreft: Stabilizers
Subject: Horizontal stabilizer hinge bolt locking.

Description:
Airworthiness Directive (BLA) 79-89-55 required a one time inspection of the stabilizer hinge bolt locking.

To prevent the hinge bolt moving outward after the loss of the cotterpin and the nut a bracket opposite to the bolthead has been designed.

Van toepassing op: F28 Aircraft Serial Numbers:
Applies to: 11003 to 11145 inclusive, 11147, 11150, 11151, 11991 and 11992.

The change will be incorporated, prior to delivery, on aircraft serial numbers 11146, 11148, 11149, 11152 to 11181 inclusive.

Tijdstip van uitvoering: Required before October 1, 1980.
Compliance date:

Reason for revision: To amend the affected aircraft.

This BLA supersedes the foregoing BLA 80-37-55 with publication number 80/53, dated May 16, 1980.

Datum van inwerking-
treding: July 26, 1983
Effective date:

Uitvoering: In accordance with Fokker Service Bulletin
Accomplishment: F.28/55-21 rev. 1, dated May 30, 1983 or later
RLD approved revision.