

Ministerie van Verkeer en Waterstaat
Rijksluchtvaartdienst

BLA

Luchtvaartinspectie

(publ. Nr. 81/119)
23 Nov.

Schiphol-Oost - Gebouw 144 - Stationsplein - Telefoon 020 - 5169111

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 uitg. 4 en BLA nr. 74-70-00 uitg. 4 maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA Nr 81-19-28 issue 2

FOKKER F.27

Betreft: Fuel tank ventilation - one time inspection of
Subject: drain tubing to vent float valve and sniffle valve.

Reason for revision: Correction of the aircraft serial numbers.

Description:

Via Fokker spare parts department some rubber sleeves of non fuel resistant material may have been delivered to operators as a replacement for sleeves in the fuel vent system. Part I of this Airworthiness Directive calls for an inspection and if necessary temporarily installation of a locally obtained fuel resistant hose. Further the effected page in the IPC shall be corrected. Part II calls for the replacement of the drain tubing.

Van toepassing

op: F.27 Aircraft Serial Numbers:

Applies to: Configuration I:
Aircraft serial numbers 10102, 10103, 10131 to 10181 inclusive and 10184 to 10601 inclusive.

Configuration II:

Aircraft serial numbers 10105, 10106, 10107, 10108, 10109, 10110, 10111, 10113, 10114, 10116, 10118, 10119, 10120, 10121, 10122, 10124, 10125, 10127 and 10183. Aircraft serial numbers 10602 and subsequent are not effected, as the IPC for these aircraft has been updated which assures installation of sleeves of correct material.

Tijdstip van uitvoering: Part I : Before June 1,1981
Compliance: Part II : Before December 31,1981

Datum van inwerkingtreding:
Effective date: November 25, 1981

Uitvoering: In accordance with Fokker Service
Accomplishment: Bulletin F.27/28-55 dated April 15, 1981
or later RLD approved revision.

Vervallen: BLA-81-19-28 (Publ. nr 81/29),
Cancelled: Dated April 15, 1981

All operators of the above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O. Box 7555
1117 ZH SCHIPHOL
The Netherlands
Telex: 15267 rldli nl
Telef.: 020 - 5163278