

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation



directie luchtvaartinspectie
Aeronautical Inspection Directorate

BLA nr. 88 - 23

Date: March 30, 1988 / 31

F O K K E R

Type: F.27-050

Seq.: 004

postbus 7555 1117 ZH schiphol-oost the netherlands tel. (020) 5 16 91 11

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

POWER PLANT - RIGHT HINGED COWL DOOR AIR INTAKE - MODIFICATION

Description:

To ensure free movement of the engine power levers, which may block in icing conditions due to freezing.

The modification of the air intake keeps the ventilation airflow away from the engine-control rod-box.

Effectivity:

F.27 Mk.050 aircraft serial numbers:

20103 to 20108 inclusive; and 20110 to 20116 inclusive.

Effective date: April 08, 1988

Compliance: required before June 01, 1988

Accomplishment: In accordance with Fokker Service Bulletin F50-71-003 dated April 08, 1988 or a later RLD-approved revision.

Remarks:

- 1) In respect to art. 88 par. 3 of the State Control of Aviation Act, this Airworthiness Directive (BLA) has to be accomplished by or under supervision of an approved company.
- 2) All operators of the affected aircraft are receiving the ref. Service Bulletin directly from the manufacturer.

Note:

Adress inquiries regarding this AD to:

Civil Aviation Department

Aeronautical Inspection Directorate

P.O. Box 7555, 1117 ZH Schiphol Airport, The Netherlands

Telex: 15267 rldli nl, Telephone: ()-31-(0)20-516 32 78

ISSN 0920 - 1084