

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation

directie luchtvaartinspectie
Aeronautical Inspection Directorate



Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

BLA nr. 89 - 67

Date : June 09, 1989

F O K K E R

Type : F.28-0100

Seq. : 027

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

FLIGHT CONTROLS - ELEVATOR CONTROL SYSTEM - MODIFICATION

Description:

A spring bungee is installed in the mechanical elevator control-system, to return the control columns to a balanced condition when the elevators are neutral. The spring bungee is installed below the floor between the elevator input quadrant and the structure, on the right side of the flight compartment. Service experience has shown that the spring bungee can cause an increase in system loads during some maneuvers. To smooth out the increase in system loads, this Airworthiness Directive (BLA) calls for the existing square-shoulder bush in the spring bungee to be replaced by a tapered-shoulder bush.

Effectivity:

F.28 Mk.0100 aircraft serial numbers:
11244, 11248 to 11256 inclusive and 11268.

Effective date: June 16, 1989

Compliance: required before August 01, 1989

Accomplishment: In accordance with Fokker Service Bulletin F100-27-012 dated June 02, 1989 or a later RLD-approved revision.

Remarks:

- In respect to art. 88 par. 3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft are receiving the ref. Service Bulletin directly from the manufacturer.

Note:

Address inquiries regarding this AD to:
Department of Civil Aviation
Aeronautical Inspection Directorate
P.O. Box 575, 2130 AN Hoofddorp, The Netherlands
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503 - 63161
Telefax: ()-31-(0)2503 - 40741