

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation

BLA nr. 89 - 78



directie luchtvaartinspectie
Aeronautical Inspection Directorate

Date : July 12, 1989

F O K K E R

Type: F.27 - 050

Seq.: 044

Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

In der authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

AIR CONDITIONING - INSTRUMENT COOLING AIR SPRAY PIPE - MODIFICATION

Description:

On several occasions in flight, the Cool Fan Inoperative warning light in the Flight Compartment illuminated, indicating that the cooling fan did not supply enough cool air for the Electronic Flight Instrument System (EFIS). To increase the cool air flow rate, this Airworthiness Directive (BLA) calls for the holes in the air spray pipe behind the main instrument panel to be made larger.

Effectivity:

F.27 Mk.050 aircraft serial numbers:

20103 to 20108 inclusive and 20110 to 20117 inclusive.

Effective date: July 19, 1989

Compliance: required before June 01, 1990.

Accomplishment: In accordance with Fokker Service Bulletin F50-21-005 dated June 30, 1989 or a later RLD-approved revision.

Remarks:

- In respect to art.88 par.3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.

Note:

Address inquiries regarding this AD to:

Department of Civil Aviation
Aeronautical Inspection Directorate
P.O.Box 575 2130 AN Hoofddorp, The Netherlands
Telex: 74592 rldli nl Telephone: ()-31-(0)2503-63163
Telefax: ()-31-(0)2503-40741