

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation

directie luchtvaartinspectie
Aeronautical Inspection Directorate



Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

BLA nr. 89-110

Date : September 25, 1989

F O K K E R

Type: F.27-050

Seq.: 055

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)**

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

FUSELAGE - UPPER GIRDER CONNECTION AT STA.3415 - REINFORCEMENT

Description:

During full-scale fatigue testing, cracks were found in the angle-type fitting at fuselage STA.3415, between the upper girder of the flight compartment window and the upper torsion box of the passenger door. This fitting proved to have an insufficient fatigue life.

This Airworthiness Directive (BLA) calls for the introduction of an additional reinforcement bracket, which will improve the fatigue life of subject girder connection.

Effectivity:

F.27 Mk.050 aircraft serial numbers:

20103 to 20108 inclusive and 20110 to 20147 inclusive.

Effective date: September 29, 1989

Compliance: required before accumulating 10,000 flight cycles.

Accomplishment: In accordance with Fokker Service Bulletin F50-53-020 dated September 15, 1989 or a later RLD-approved revision.

Remarks:

- In respect to art. 88 par 3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.

Note: Address inquiries regarding this AD to:

Department of Civil Aviation
Aeronautical Inspection Directorate
P.O. Box 575, 2130 AN Hoofddorp, the Netherlands
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503-63163
Telefax: ()-31-(0)2503-40741