

ministerie van verkeer en waterstaat  
*Ministry of Transport and Public Works*

**rijksluchtvaartdienst**  
*Department of Civil Aviation*

**directie luchtvaartinspectie**  
*Aeronautical Inspection Directorate*



Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

BLA nr: 90-141 issue 2

Date : September 06, 1991

F O K K E R

Type: F.28 Mk.0100

Seq.: 070

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING  
(BLA)  
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.*

**FUSELAGE - SHEAR PLATE RIVETS AT STA.20320 - INSTALLATION**

**Description:**

During production, it was found that on some aircraft, not all the rivets which attach the flange of the shear plate at stringer 59 to fuselage STA.20320 were installed. To correct this oversight, this Airworthiness Directive (BLA) requires, where necessary, the installation of rivets in the affected shear plate.

**Effectivity:**

**F.28 Mk.0100 aircraft serial numbers:**  
11268 to 11273 inclusive, 11276, 11278 and 11280

**Effective date:** issue 1: December 21, 1990  
issue 2: September 13, 1991

**Compliance:** required before accumulating 6,000 flight cycles or three (3) years time since new (TSN), whichever comes first.

**Accomplishment:** in accordance with Fokker Service Bulletin F100-53-048 revision 1 dated August 19, 1991 or a later RLD-approved revision.

**Reason for revision:** issue 2: Clarification of "Description".

**Remarks:**

- In respect to Art.88 par.3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.

**Note:** Address inquiries regarding this AD to:

Department of Civil Aviation  
Aeronautical Inspection Directorate  
P.O. Box 575, 2130 AN Hoofddorp, the Netherlands  
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503-63168 or -63122  
Telefax: ()-31-(0)2503-40741