

ministerie van verkeer en waterstaat
Ministry of Transport and Public Works

rijksluchtvaartdienst
Department of Civil Aviation

directie luchtvaartinspectie
Aeronautical Inspection Directorate



BLA nr: 91-020

Date : March 01, 1991

F O K K E R

Type: F.27 Mk.050

Seq.: 092

Postbus 575 2130 AN Hoofddorp Tel. 02503 - 63131

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

**LANDING GEAR - ALTERNATE GEAR HANDLE- & GUSTLOCK LEVER THUMB LOCK RELEASE
RETAINING SCREWS - ATTACHMENT IMPROVEMENT**

Description:

On two aircraft, the retaining screw for the thumb plate on the ALTERNATE landing gear selector handle has been found to have become detached. This prevented inwards movement of the lockpin into the handle, making it nearly impossible to disengage the handle before selection. As the gustlock lever has a similar thumb plate installed and to prevent loose screws from becoming the cause of incidents, this Airworthiness Directive (BLA) requires the application of 'LOCTITE' to the threads of the affected thumb plate retaining screws.

Effectivity:

F.27 Mk.050 aircraft serial numbers:
20103 to 20199 inclusive

Effective date: March 08, 1991

Compliance: required before August 01, 1991

Accomplishment: in accordance with Fokker Service Bulletin F50-32-015 dated February 12, 1991 or a later RLD-approved revision.

Remarks:

- In respect to Art.88 par.3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.

Note: Address inquiries regarding this AD to:

Department of Civil Aviation
Aeronautical Inspection Directorate
P.O. Box 575, 2130 AN Hoofddorp, the Netherlands
Telex: 74592 rldli nl, Telephone: ()-31-(0)2503-63120 or -63162
Telefax: ()-31-(0)2503-40741
ISSN 0920 - 1084