

AIRWORTHINESS DIRECTIVE OF THE NETHERLANDS

(Bijzondere Luchtwaardigheids Aanwijzing - BLA)



Ministry of Transport, Public Works and Water Management

Directorate-General of Civil Aviation

Aeronautical Inspection Directorate

BLA nr: 92-051

Date : April 08, 1992

F O K K E R

Type: F.28 Mk.0100

Seq.: 098

Postbus 575 2130 AN Hoofddorp Tel.02503-63131

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de Directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Civil Air Navigation Regulations (RTL), the Director Aeronautical Inspection of the Civil Aviation Department issues the following Airworthiness Directive.

FLIGHT CONTROLS - HORIZONTAL STABILIZER/ACTUATOR ATTACH LINK BOLTS - REPLACEMENT

Description:

The bolts P/N D03000-017, which attach the link assemblies on the horizontal stabilizer dual actuator to the horizontal stabilizer drive bracket, have not received the proper surface treatment. This condition, if not corrected, makes the bolts prone to corrosion, which may result in premature fatigue cracking of the bolt. Since this unsafe condition is likely to exist or develop on other aircraft of this same type design, this Airworthiness Directive (BLA) requires the replacement of the affected bolts with improved bolts P/N D03000-021 with a longer fatigue life.

Effectivity:

F.28 Mk.0100 aircraft serial numbers:

11244 to 11300 inclusive, 11303, 11306, 11308, 11310, 11312, 11313 and 11314

Effective date: April 15, 1992

Compliance: required before accumulating 13,500 flight cycles

Accomplishment: In accordance with Fokker Service Bulletin F100-27-037 dated April 03, 1992 or a later RLD-approved revision.

Remarks:

- In respect to art. 88 par 3 of the Civil Air Navigation Regulations, this Airworthiness Directive (BLA) must be accomplished by or under supervision of an approved company.
- All operators of the affected aircraft have received the ref. Service Bulletin directly from the manufacturer.

Note: Address inquiries regarding this AD to:

Department of Civil Aviation
Aeronautical Inspection Directorate
P.O. Box 575, 2130 AN Hoofddorp, the Netherlands
Telex: 74592 rldli nl, Telephone: (-)31-(0)2503-63122 or -63168
Telefax: (-)31-(0)2503-40741
